



## MODEL LN-PSW-SA: ADAPTER FOR SUREFIRE® REMOTE PRESSURE SWITCH

To use the adapter first remove the battery cap from your infrared illuminator, then attach the adapter's covered threaded side (1) in place of the battery cap.

Use the copper washers included with the adapter to provide reliable contact between the adapter and the cap by placing one or both washers on the bottom plate of the Surefire cap (some caps will require only single washer, some will require both).

Attach the Surefire remote pressure switch cap onto the exposed threaded part (2) of the adapter.

The setup is now ready for operation.

Should you have any questions regarding operation or mounting of this adapter, please do not hesitate to give us a call at 972-722-1100 or E-mail us at: [info@lunaoptics.com](mailto:info@lunaoptics.com)

